

Work Order #: W20513 	WorkOrder Freedom Aero Service Inc. Certified Repair Station # 25FR283B EASA145.6177 3200 Howard St McClellan, CA 95652 PH: 916-434-5194 FX: 916-434-5637	Work Type: Repair Priority: Routine Warranty: No Page: 1 of 1
--	---	--

Customer: RotorLink Technical Services PN: 355A61-5210-0001 Qty: 1	Description: PC Board Discrepancy	Cust PO: R2019-84D TSN: TSO: TSR:
---	--	--

Specification: Repair spec FRS-6 Rev. ORG 09/02/16 Hidden Damage: N/A Serial Number(s): FAS20513 Searched for applicable AD's: None found
--

Task: Preliminary Inspection

Start:  182877S	Stop or Complete:  182877C
--	---

Preliminary Inspection

Action: Reg No: N/A, A/C Eng. Serial No: 5045, Wo: P2017-29. Unit received with 3 missing fuse holders and 1 damaged holder. PCB requires cleaning and resoldering of all of the larger .25inch fuse holders.

Inspected by: Mike Johnson 10/16/2019 4:51:35 PM

Task: Repair/In Process Insp

Start:  182881S	Stop or Complete:  182881C
---	--

Repair/In Process Insp

Action: Repaired; Replaced 3 missing large fuse holders and 1 damaged holder. PCB cleaned and resoldered all of the large fuse holders. Repaired all questionable solder joints. Replaced 1 missing and 1 broken small fuse holder. Found a broken wall on Connector C that required replacing, connector C was replaced. Unit was tested in accordance with Repair spec FRS-6 and passes all test.

Inspected by: Mike Johnson 2/20/2020 11:18:26 AM

Task: Final Inspection

Start:  182882S	Stop or Complete:  182882C
--	---

Final Inspection

Action: Inspected.

Inspected by: Mike Johnson 2/20/2020 11:18:38 AM

Maintenance Release: The appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and, with respect to the work performed, is airworthy and approved for return to service.

Kevin Sherman

Name (Typed or Printed)

Authorized Signature

Date

Inspectors Stamp

2/20/20

