

Organization Name and Address: Freedom Aero Service Inc.  
 3200 Howard Street  
 McClellan, CA 95652  
 USA  
 Ph: 916 434-5194, Fax: 916 431-5637  
 FAA Approval Holder: 25FR283B

5. Work Order, Contract or Invoice Number:  
**W20557**


Item	Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	Alpha PC Board	355A67-7532-02	1	FAS20557	INSPECTED/TESTED

12. REMARKS  
 INSPECTED/TESTED in accordance with Repair spec FRS-6 Rev.ORG, 09/02/16  
 Full details of work held on work order No: W20557  
 Certifies work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the article is considered ready for release to service under EASA Part 145 Approval Number EASA 145-6177

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.  
 Non-approved design data specified in Block 13

14a  14 CFR 43.9 Return to Service  Other regulation specified in Block 12  
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and with respect to that work, the items are approved for return to service.

13b. Authorized Signature: \_\_\_\_\_ 13c. Approval Authorization No: \_\_\_\_\_ 14b. Authorized Signature:  14c. Approval/Certificate No: 25FR283B

13d. Name (Typed or Printed): \_\_\_\_\_ 13e. Date (dd/mmm/yyyy): \_\_\_\_\_ 14d. Name (Typed or Printed): **Kevin Sherman** 14e. Date (dd/mmm/yyyy): 18/Oct/2019

**User/Installer Responsibilities**

It is important to understand that the existence of this document alone does not automatically constitute authority to install the engine/propeller/article.  
 Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.  
 Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Work Order #:  
W20557



### WorkOrder

Freedom Aero Service Inc.  
Certified Repair Station # 25FR2831  
EASA145.6177  
3200 Howard St McClellan, CA 95652  
PH: 916-434-5194 FX: 916-434-5637

Work Type: Repair  
Priority: Routine  
Warranty: No  
Page: 1 of 1

Customer: RotorLink Technical Services  
PN: 355A67-7532-02  
Qty: 1

Description: Alpha PC Board  
Discrepancy

Cust PO: R2019-84D

TSN:  
TSO:  
TSR:

Specification: Repair spec FRS-6 Rev.ORG, 09/02/16

Hidden Damage: N/A

Searched for applicable AD's: None found

Serial Number(s): FAS20557

#### Task: Preliminary Inspection

Start:



183207S

Preliminary Inspection

Stop or Complete:



183207C

Action: Removed from Reg: N/A, S/N: 5752, W/O: 10471A. Unit passes all preliminary test and is in good condition.

Inspected by: Mike Johnson 10/9/2019 1:06:38 PM

#### Task: Repair/In Process Insp

Start:



183211S

Repair/In Process Insp

Stop or Complete:



183211C

Action: Tested; Unit was tested in accordance with FRS-6 and passes all test.

Inspected by: Mike Johnson 10/9/2019 1:06:43 PM

#### Task: Final Inspection

Start:



183212S

Final Inspection

Stop or Complete:



183212C

Action: Inspected.

Inspected by: Mike Johnson 10/9/2019 1:06:53 PM

Maintenance Release: The appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and, with respect to the work performed, is airworthy and approved for return to service.

Kevin Sherman

Name (Typed or Printed)

Authorized Signature

Date

10/18/19

Inspectors Stamp

