1. Approving National Aviation 2.			3. Form Tracking Num	Form Tracking Number.	
Authority/Country:	AUTHORIZED RELE	87471			
FAA/UNITED STATES	FAA/UNITED STATES FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				
4. Organization Name and Address.	S. Freedom Aero Service Inc. 3200 Howard Street McClellan, CA 95652 USA Ph: 916 434-5194, Fax: 916 431-5637		5. Work Order, Contract or Invoice Number: W20543		
FAA Approval Holder: 25FR283B					
6. Item 7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1 Alpha PC Board	355A67-9516-01	1	FAS20543	REPAIRED	
12. REMARKS					
REPAIRED in accordance with Repair spec FRS-6 Rev. ORG 09/02/16 Full details of work held on work order No: W20543 Certifies work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the article is considered ready for release to service under EASA Part 145 Approval Number EASA 145-6177 13a. Certifies the items identified above were manufactured in conformity to: Approved design data and are in a condition for safe operation. Non-approved design data specified in Block 13 Approved design data specified in Block 13 Approved design data specified in Block 13 Approved design data specified in Block 13					
13b. Authorized Signature:	13c. Approval Authorization No:	14b. Authorized Signature:	14c. Approval/	Certificate No:	
			25FR283B		
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/	mmm/yyyy):	
		Kevin Sherman	02/Dec/2019		
	User/In	staller Responsibilities			
Where the user/installer performs wor essential that the user/installer ensure	existence of this document alone does not automatic k in accordance with the national regulations of an a set that his/her airworthiness authority accepts aircrain to constitute installation certification. In all cases air before the aircraft may be flown.	airworthiness authority different than the airworthiness from the airworth (s)/propeller(s)/article(s) from the airworthiness authority different than the	thiness authority of the countri orthiness authority of the coun	ntry specified in Block 1.	

Work Order #: W20543



WorkOrder

Freedom Aero Service Inc.
Certified Repair Station # 25FR283B
EASA145.6177

3200 Howard St McClellan, CA 95652 PH: 916-434-5194 FX: 916-434-5637 Work Type: Repair
Priority: Routine
Warranty: No

Cust PO: R2019-84D

Page: 1 of 1

Customer: RotorLink Technical Services

PN: 355A67-9516-01

Description: Alpha PC Board

TSN: TSO:

Qty: 1

Discrepancy

TSR:

Specification: Repair spec FRS-6 Rev. ORG 09/02/16

Hidden Damage: N/A

Searched for applicable AD's: None found

Serial Number(s): FAS20543

Task: Preliminary Inspection

Start:



183109S

Stop or Complete:



1831090

Preliminary Inspection

Action: Reg.No: N/A, A/C Eng. Serial No: 5752, Wo: 10471A. Unit received in good condition. PCB requires cleaning.

Inspected by: Mike Johnson 10/21/2019 3:19:43 PM

Task: Repair/In Process Insp

Start:



183113S

Stop or Complete:



1831130

Repair/In Process Insp

Action: Repaired: PCB cleaned. Unit passes all tests in accordance with Repair spec FRS-6 Rev. ORG 09/02/16.

Inspected by: Mike Johnson 10/21/2019 3:19:53 PM

Task: Final Inspection

Start:



.831145

Final Inspection
Action: Inspected.

Stop or Complete:



183114C

Inspected by: Mike Johnson 10/21/2019 3:20:00 PM

Maintenance Release: The appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and, with respect to the work performed, is airworthy and approved for return to service.

Kevin Sherman

Name (Typed or Printed)

Authorized Signature

0 0 1

Inspectors Stamp