1. Approving National Aviation 2.			Form Tracking Number.	
Authority/Country: AUTHORIZED RELEASE CERTIFICATE		87470		
FAA/UNITED STATES FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				
4. Organization Name and Address.	Freedom Aero Service Inc. 3200 Howard Street McClellan, CA 95652 USA Ph: 916 434-5194, Fax: 916 431-5637		5. Work Order, Contract or Invoice Number: W20542	
C 14	FAA Approval Holder: 25FR283B	L O Overtibus	I do O del Newsbarr	I 11. Status/Work:
6. Item 7. Description: 1 30 Delta Board	8. Part Number: 355A61-5116-07	9. Quantity:	10. Serial Number:	
12. REMARKS	333/101-3110-07	1	FAS20542	INSPECTED/TESTED
Certifies work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the article is considered ready for release to service under EASA Part 145 Approval Number EASA 145-6177  13a. Certifies the items identified above were manufactured in conformity to:  Approved design data and are in a condition for safe operation.  Non-approved design data specified in Block 13  Approved design data specified in Block 13  Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and with respect to that work, the items are approved for return to service.				
13b. Authorized Signature:	13c. Approval Authorization No:	14b. Authorized Signature:	14c. Approval/Certificate No: 25FR283B	
13d. Name (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed):  Kevin Sherman	14e. Date (dd/mm 18/Oct/2019	im/yyyy):
	User/In:	staller Responsibilities		
It is important to understand that the existence of this document alone does not automatically constitute authority to install the engine/propeller/article.				
essential that the user/installer ensure	c in accordance with the national regulations of an a s that his/her airworthiness authority accepts aircraf	ft engine(s)/propeller(s)/article(s) from the airwo	orthiness authority of the country	specified in Block 1.
Statement in Blocks 13a and 14a do n national regulations by the user/install	ot constitute installation certification. In all cases air er before the aircraft may be flown.	rcraft maintenance records must contain an inst	tallation certification issued in ac	ccordance with the

FAA Form 8130-3 (02-14) NSN:0052-00-012-9005

## Work Order #: W20542



## WorkOrder

Freedom Aero Service Inc. Certified Repair Station # 25FR283B EASA145.6177

3200 Howard St McClellan, CA 95652 PH: 916-434-5194 FX: 916-434-5637 Work Type: Repair Priority: Routine

Cust PO: R2019-84D

Warranty: No Page: 1 of 1

Customer: RotorLink Technical Services

PN: 355A61-5116-07

Description: 30 Delta Board

TSN: TSO:

Qty: 1

Discrepancy

TSR:

Specification: Repair spec FRS-6 Rev.Org, 09/02/16

Hidden Damage: N/A

Searched for applicable AD's: None found

Serial Number(s): FAS20542

Task: Preliminary Inspection

Start:



183102S

Stop or Complete:



Preliminary Inspection

Action: Removed from Reg: CC-AHT, S/N: 5752, W/O: 10471A. Unit is still in good condition and passes all

preliminary test.

Inspected by: Mike Johnson 10/9/2019 12:56:10 PM

Task: Repair/In Process Insp



Stop or Complete:



Repair/In Process Insp

Action: Tested; Unit was tested in accordance with FRS-6 and passes all test.

Inspected by: Mike Johnson 10/9/2019 12:56:13 PM

Task: Final Inspection

Start .



183107s

Final Inspection

Action: Inspected.

Stop or Complete:



183107C

Inspected by: Mike Johnson 10/9/2019 12:56:24 PM

Maintenance Release: The appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and, with respect to the work performed, is airworthy and approved for return to service.

Kevin Sherman

Name (Typed or Printed)

**Authorized Signature** 

Inspectors Stamp

Date