Approving National Aviation Authority/Country:		AUTHORIZED RELEASE CERTIFICATE		3. Form Tracking Number. 87648		
						FAA/UNITED STATES
4. Organization Name and Address.		Freedom Aero Service Inc. 3200 Howard Street McClellan, CA 95652 USA Ph: 916 434-5194, Fax: 916 431-5637 FAA Approval Holder: 25FR283B		5. Work Order, Contract or Invoice Number: W20605		
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
1	PCB, fire detection	704A32832000	1	FAS20605	REPAIRED	
REPAIRED in accordance with Repair spec FRS-6 Rev orig, 09/02/16 Full details of work held on work order No: W20605 Certifies work specified in Blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the article is considered ready for release to service under EASA Part 145 Approval Number EASA 145-6177 13a. Certifies the items identified above were manufactured in conformity to: 14a X 14 CFR 43.9 Return to Service X Other regulation specified in Block 12						
Approved design data and are in a condition for safe operation. Non-approved design data specified in Block 13			Certifies that unless otherwise specifies that unless otherwise specifies described in Block 12 was accomplised in	Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and with respect to that work, the items are approved for return to		
13b. Authorized Signature: 13c. Approva		13c. Approval Authorization No:	14b. Authorized Signature:	14c. Approval/Certificate No: 25FR283B		
13d. Na	me (Typed or Printed):	13e. Date (dd/mmm/yyyy):	14d. Name (Typed or Printed): Kevin Sherman	14e. Date (dd/mmm/yyyy): 18/Oct/2019		
		. User/In	nstaller Responsibilities	•		
Where the essentia	ne user/installer performs won that the user/installer ensurent in Blocks 13a and 14a do	existence of this document alone does not automatic in accordance with the national regulations of an act that his/her airworthiness authority accepts aircrain to constitute installation certification. In all cases ailer before the aircraft may be flown.	airworthiness authority different than the airworth oft engine(s)/propeller(s)/article(s) from the airwor	iness authority of the country s thiness authority of the country	specified in Block 1.	

FAA Form 8130-3 (02-14) NSN:0052-00-012-9005

Work Order #: W20605



WorkOrder

Freedom Aero Service Inc.
Certified Repair Station # 25FR283B
EASA145.6177

3200 Howard St McClellan, CA 95652 PH: 916-434-5194 FX: 916-434-5637 Work Type: Repair
Priority: Routine
Warranty: No

Cust PO: R2019-84D

Page: 1 of 1

Customer: RotorLink Technical Services

PN: 704A32832000

Description: PCB, fire detection

TSN: TSO:

Qty: 1

Discrepancy

TSR:

Specification: Repair spec FRS-6 Rev orig, 09/02/16

Hidden Damage: N/A

Searched for applicable AD's: None found

Serial Number(s): FAS20605

Task: Preliminary Inspection

Start:



183607S

Stop or Complete:



183607C

Preliminary Inspection

Action: Reg No: N/A, A/C Eng. Serial No: 5045, Wo: P2017-29. Unit received in fair condition requires cleaning and

fresh conformal coating over PCB traces.

Inspected by: Mike Johnson 10/14/2019 11:11:29 AM

Task: Repair/In Process Insp

Start:



183611S

Stop or Complete:



1836110

Repair/In Process Insp

Action: Repaired: Unit cleaned and re-insulated PCB with conformal coating. Unit passes all tests in accordance with Repair spec FRS-6 Rev orig, 09/02/16.

Inspected by: Mike Johnson 10/14/2019 11:11:33 AM

Task: Final Inspection

Start:



Final Inspection Action: Inspected. Stop or Complete:



183612C

Inspected by: Mike Johnson 10/14/2019 11:11:41 AM

Date

Maintenance Release: The appliance identified above was repaired and/or inspected in accordance with current Regulations of the Federal Aviation Administration and, with respect to the work performed, is airworthy and approved for return to service.

Kevin Sherman

Name (Typed or Printed)

Authorized Signature

Inspectors Stamp